JHD:JKA 1-6 U. S. DEPARTMENT OF CONTERCE
MATICMAL BUREAU OF STANDARDS
WASHINGTON

Letter
Circular
LC784
(Supersedes
LC660)

March 26,01945

ELECTRICAL AUTERFERENCE WITH RADIO RECEPTION

Radio reception is, in some localities, seriously disturbed by interference arising from electrical apparatus in the vicinity. A brief outline of the sources of such interference and the methods usually used in mitigation is given herein, together with references to further information. No consideration is given herein to interference caused by unwanted radio stations or by devices, such as diathermy generators, which inherently operate at radio frequencies. The only general remedy for electrical interference is cooperative effort, on the part of users of radio and users or owners of the electrical sources of disturbance, to reduce or eliminate the causes of the trouble.

Much of the work in mitigation of electrical interference results in an improvement in the operation of the electrical devices or supply lines and is thus a double gain. There are, however, some electrical devices which, even when in perfect working order, cause disturbances which result in interference with radio reception. In many cases it is possible to provide filters, shields, chokes, etc., either at the source of disturbance or at the receiving set, which do much to relieve the difficulties. The cure is often difficult, requiring considerable technical knowledge and experience.

Some of the disturbance from electrical devices is practically inevitable and must be regarded, like atmospheric disturbances, as part of the inherent limitation of radio reception. In other words, the limitation upon radio reception is not primarily the distance and power of the transmitting stations and the sensitiveness of the receiving set, but the omnipresent background of electrical disturbances which drown out signals below a certain intensity. This background of electrical disturbances is the underlying reason why reception from near stations is inherently superior to reception from distant stations.

A major source of trouble is electrical apparatus in which sparks occur. Another is devices in which there are sudden electrical discharges; these include need signs and fluorescent lamps.

Sparking Apparatus.— Sparks are produced in the normal operation of many types of electrical apparatus (such as motors, motor starters, vacuum cleaners, doorbells, buzzers, oil-burners, automobile ignition systems, X-ray apparatus, violet-ray machines, some forms of battery chargers, rural telephone ringers, thermostats). Sparks are also sometimes produced at poorly designed or defective insulators or transformers, or at adjacent metal parts, of electric power lines. Sparks usually give rise to interfering electric waves which travel along the electric power wires. These waves may be carried along the power wires (sometimes many miles) to radio

receiving sets, or may produce interference by induction in a nearby receiving antenna or lead-in or radio receiving set.

One remedy for such types of interference is to eliminate the spark. This is possible if the spark is an electrical leak and not necessary to the operation of the device in which it occurs. Hany very useful electrical machines, however, require for their operation the making and breaking of electrical circuits while they are carrying current, and whenever this happens a spark is produced. In these cases the production of the spark is inherent; it is therefore necessary to make the spark of such nature or so arrange the circuits that the radio-frequency current is reduced or prevented from radiating.

Mitigation of Interference Carried by Power Lines.—
To prevent the radio-frequency current produced by a spark from getting on to the lines connecting the sparking apparatus some form of filter circuit is necessary. A condenser (1 microfarad, more or less), usually with a series resistance, connected across the sparking points will short-circuit a considerable amount of the radio-frequency current, or a condenser connected from each side of the line to "ground" will serve the same purpose.*
A choke coil in each side of the line in addition to the condensers connected to ground forms a simple filter circuit which should prevent radio frequencies from getting on the line. A high inductance (choke coil) or high resistance connected in each side of the line changes the characteristics of the circuit so as to reduce the amount of power radiated.

In some cases it is desirable to supplement the filter circuit by surrounding the apparatus by solid metal sheet or wire screen which is thoroughly grounded. The screen should completely surround the apparatus. This may be difficult. For example, in shielding the ignition system of a gasoline engine the spark coils and all wires and other parts of the system must be enclosed in metal shields and these must be very well grounded.

Where d-c motors or "universal" motors (a-c, d-c with commutator) are in operation near a radio receiving set interference is usually caused, especially when the brushes on the motor are sparking badly. The sparking should be reduced as much as possible by cleaning the commutator and proper setting of the brushes. The remaining interference is sometimes overcome by connecting a O.1-microfarad condenser between each brush holder and the frame of the motor or generator. Condensers connected between each terminal and the frame may also be helpful. All leads should be as short as possible. The condensers should have a working voltage rating at least double that of the equipment on which they are used.

^{*}When any connections are made to the power line, in order to avoid fire and personal injury, only apparatus that is carefully tested as to voltage and current-carrying capacity should be used and the power company should be consulted before making the installation. Additions to the power lines should be made only by qualified persons.

It is sometimes possible to reduce the interference by similar measures at the radio receiving set. Two O.1-microfarad condensers may be connected in series across the supply line at the outlet to which the receiving set is connected. The midpoint between the condensers is grounded to the conduit of the wiring system.

Mitigation of Induced Interference.— The electrical interference is in some cases not carried into the receiving set by the power lines but is instead induced in the antenna or lead—in or receiving set by interfering devices or power lines nearby.

Such interference may be reduced by shielding the receiving set and lead-in and installing the antenna well above the building and away from power lines. However, the shielding of the lead-in is a specialized operation. In one arrangement it is done by connecting the antenna as a doublet, using a twisted-pair cord as a lead-in from the doublet antenna to the receiving set, and using a matching transformer between the receiving set, and the lead-in; this method is generally applied for the high frequencies (short waves). For the ordinary broadcast frequencies (550 to 1600 kilocycles), a feasible method is to use impedance matching transformers at the antenna end and the receiver end of the lead-in.

Another method of mitigation is use of a directional receiving antenna. This is usually a shielded loop antenna, which is easily tuned so as to minimize the received interference.

Location of Source of Interference .- The first thing to do in tracing the source of trouble is to make sure that there are no loose connections or defective parts in the receiving set itself. The next thing is to determine whether the source of trouble is in electric devices in the house; this is done by completely disconnecting all electric cords and appliances from the sockets or outlets, and removing all lamp bulbs or else screwing them in tight. Tight contacts in all electric equipment are essential. If the interfering noise is still heard in the radio receiving set, it is then desirable to report the situation to the electric power company. Many of the companies have appeartus for the purpose of following up complaints of this kind. Usually a receiving set with a coil antenna is used to determine the direction from which the interfering noise comes, and this outfit is taken from place to place until the source is found. location of such sources is often a very difficult and baffling undertaking. It sometimes requires that the power be cut off of parts of the line, in order to trace down the part of the line where the trouble arises. The trouble sometimes comes from a spark discharge over an insulator to ground, or between a pair of wires, or it may be that the wire is touching some object such as a tree, pole, guy wire, etc. Power-line hardware is a cause of much interference, if not properly installed. Insulated tie wires become sources of interference after the insulation deteriorates. A spark discharge is a loss of power to the operating company and a potential source of serious trouble, and for these reasons the company is probably more interested in finding and eliminating this type of trouble than the radio listener. Large leaks and sparks may be observed at night, especially in wet weather. However, sparks which are too small to be readily noticeable cause serious interference to radio reception.

Precipitators - Radio interference may be caused by the electrical precipitators used to prevent smoke and noxious fumes or materials from leaving chimneys. The precipitator operates by establishing a highly charged electric field inside the chimney of such a nature and direction that particles going up the chimney are charged and driven against the walls where they stick. Precipitators cause interference for the reason that the high voltage used in their operation is obtained from a rectifier which produces sparks and generates radio-frequency alternating currents as well as the direct current which the precipitators need. If the precipitator is so designed and arranged that the distance between the rectifier and the chimney is only a few feet or if the entire apparatus including all leads is housed in a metal building there is usually no trouble. But if the rectifier is separated from the chimney, the wire that joins them forms a good antenna which will radiate and cause interference for 20 miles or more.: Interference from these precipitators can be eliminated by placing a grounded wire" screen entirely around these wires and thoroughly grounding the wire screen and the rectifier. If screening of the various parts is impracticable, damping resistances can be inserted at various points in the wire line which will reduce the amount of power radiated. Tuned circuits connected across the spark gap of the rectifier will assist by absorbing the radio-frequency power.

Sources of Further Information.— Articles frequently appear in technical magazines on the mitigation of electrical interference. The following list, arranged chronologically, gives representative references to such articles. Except where noted, they are not issued by, and are not available from the Pational Bureau of Standards. These publications can be consulted in public libraries which maintain files of periodicals, or copies may be secured from the publishers at the following addresses:

Bell Laboratories Record. 463 West St., New York 14, F.Y. Chemical & Metallurgical Engineering. McGraw-Hill Bldg.

330 West 42nd St., New York 18, N.Y.

Electrical Engineering, 33 West 39th St., New York 18, N.Y.,

Electrical World. 330 West 42nd St., New York, 18, N.Y.,

Electronics. McGraw-Hill Bldg., 330 West 42nd St., New York 18, N.Y.

Iowa Engineering Experiment Station. Lowa State College, Ames, Iowa,

Journal of the Averican Institute of Electrical Engineers.

33 West 39th St., New York 18, N.Y.

Journal of the Institution of Electrical Engineers. Savoy Place, Victoria Embankment, Jondon W.C.2, England.

National Electric Light Association (now Edison Electric Institute). 420 Lexington Avenue, New York 17, N. Y.

Proceedings of the Institute of Endio Engineers. 330 West 12nd St., New York 18, N.Y.

QST. American Regio Relay League, West Hartford, Conn.

Radio. 342 Madison Avenue, New York City.

Radio Branch, Dept. of Marine and Fisheries, Ottawa, Canada.

Radio Craft. Rad-Craft Publications Inc., 25 N. Broadway, New York 7, N.Y.

Radio Manufacturers Association. 1317 F.St., N.W., Washington 4, D. C. Radio News. Ziff-Davis Publishing Co., 540 N. Michigan Ave., Chicago 11, Ill. Sherwood Press. Box 552, Edgewater Branch, Cleveland, Ohio.

Telegraphen-Fernsprech-Funk und Fernsehen-Technik. Published by Richard Dietz, Berlin W62, Wichmannstrasse 5, Germany. Tobe Deutschmann Corp., Canton. Mass.

Transactions of the American Institute of Electrical Engineers (and Electrical Engineering), 33 West 39th St., New York City.

Wireless Engineer Iliffe & Sons, Ltd., Dorset House, Stamford St.,

London, S.E.1, England.
Wireless World, Iliffe & Sons, Ltd., Dorset House, Stamford St., London, S.E.1. England.

In each reference below, unless otherwise indicated, the first number (underscored) is the volume of the periodical; the numbers following indicate pages and the year of publication. Wames of periodicals abbreviated can be found in full in the list of addresses above.

- Radio interference. (Serial Report of the Inductive Coordination Committee, 1924, 1925). Publication No. 25-63, National Elec. Light Assoc. (1925).
- Radio Inductive interference. Bulletin No. 1, Radio Branch, Dept. of Marine and Fisheries, Ottawa, Canada. (1925). 15 cents.
- Interference. N. W. McLachlan. Vireless World and Radio Review 16, 79-81; 201-203; 391-394 (1925); 17, 84-87 (1925).
- The radio interference problem and the power company. A. J. Corbett. Jnl. A.I.E.E. 44, 1057 (1925). 1
- Correction of radio interference from Cottrell precipitators. J. J. Jakosky. Chem. & Met. Eng. 33, 221 (1926).
- Radio interference caused by poorly grounded cable sheath. F. Krug. Elec. Wld. 87, 718 (1926).
- Radio interference from power lines. P. S. Donnell. Radio 8, pp. 31-32 of June (1921).
- Radio interference (man-made interference largely controllable test equipment described by Southern California Edison Co.) R.B. Ashbrook and R. W. Wight. Elec. Wld. 88, 851 (1926).
- Cures for power leaks. R. S. Kruse. QST 11, pp. 9-14 of March (1927).
- Location of radio interference (equipment used, procedure followed, etc.). B. E. Ell'sworth. Elec. Wld. 89, 810 (1927).
- Man-made static High voltage overhead electrical transmission lines and 📑 radio interference. R. L. Smith-Rose. Wireless Wld. & Radio Rev. 24, 476 (1929).

- Radio interference. J. C. Allen. Proc.I.R.E. 17, 882 (1929).
- Radio noises and weir cure. Pamphlet with advertising. Tobe Deutschmann Corp. (1932). 50 cents.
- The location and elimination of radio interference. J. K. McNeely. Iowa Eng. Exp. Sta. Bulletin 105 (1931).
- Reduction of radio interference from telephone power plants. J. M. Duguid.

 Bell Labs. Record 10, 124-(1931).
- Radio interference. Radio News 13, 560 (1932).
- A balanced wave trap. V. S. Percival. Wireless Wld 31, 274 (1932).
- Radio interference. M. D. Hooven, Jr. Sec. 26, pp. 96-129, Standard Handbook for Electrical Engineers, 6th ed. (1933). McGraw-Hill Book Co., Price \$7.00.
- Reducing man-made static. G. H. Browning. Electronics 5, 366 (1932).
 Radio Craft 4, 412 (1933).
- Avoidable interference. A.L.J.Bernsert. Wireless Wld. 33, 4 (1933).
- Wireless under way -- Suppressing radiation from car electrical systems.
 Wireless Wld. 33, 18 (1933).
- Suppression of radio interference with capacity type filters. C. V. Aggers and W. E. Pakela. Elec. Jnl. 30, 337 (1933).
- Problems of electrical interference. A. Morris. Wireless Wld. 33, 144 (1933).
- Reducing radio interference from commutating machines. C. V. Aggers and W. E. Pakela. Elec. Jnl. 30, 423 (1933).
- Radio noise. . H. Scott. Radio News 15, 278 (1933).
- Suppressing auto radio noise. G. Browning. Radio News 15, 110 (1934).
- The interference of electrical plant with the reception of radio broadcasting.

 A. Morris. Jnl.I.E.E. (London) 74, 245 (1934).
- Radio interference from synchronous converters. C. V. Aggers and W. E. Pakela. Elec. Jnl. 31, 121 (1934).
- Suppression of radio interference using tuned choke coils. C. V. Aggers and R. N. Stoddard. Elec. Jnl. 31, 305 (1934).
- Plan to eliminate radio interference. Electronics 7, 370 (1934).

- Diathermy interference. R. L. Haskins. Radio Eng. 15, 2.20 of Feb. (1935).
- Electrical interference with broadcasting. Jnl.I.E.E. (London) 79; 206 (1936).
- Good radio reception. R.M.A. Engineering Bulletin 19. ladio Manufacturers Association. (1936).
- Interference source discovered. (Diathermy). Electroniss 9, p.9 of Feb. (1936).
- Radio interference and its suppression. J. H. Reymer. The Sherwood Press. Price \$4.00.
- Chasing down interference. Radio #218, pp.92-93 of April (1937).
- Radio interference from street railway systems. L. M. Frew. Proc.I.R.E. 25, 708 (1937).
- Eliminating radio interference. C. V. Aggers. Electric Journal 34, 331 (1937).
- A review of radio interference investigations. F. E. Sanford and W. Weise. Elec. Engineering 56, 1248 (1937).
- Interference elimination. (Pamphlet). Aerovox Research Worker 9, No. 1 (Jan. 1937).
- The causes and elimination of radio interference. (Book). J. E. Foster. Published by C. W. Nelson Co., Braintree, Mass.
- Further notes on the reduction of BCL interference. G. W. Ewing. Radio #227, pp.19-20 of March (1938).
- RF interference from power circuits Identifying and curing radio noises.
 R. Y. Chapman. QST 22, p.49 of March (1938).
- Canada's interference detectives. Radio Craft 9, pp.686-687 of April (1938).
- References on radio interference. L. F. Roehman. Electronics 11,,p.32 of Oct. (1938).
- Radio interference investigation, suppression and control. H. O. Merriman and F. G. Nixon. Proc.I.R.E. 27, 16 (1939).
- The diagnosis and cure of radio noise. (Pamphlet with advertising). Aerovox Corporation, N. Medford, Mass.
- Using condensers for eliminating interference from electric tramways.

 L. Lemaine. Vireless Engineer (London) 16, 3 (1939).
- The ultra-short wave interference suppression of the electrical ignition system of motor vehicles. W. Scholz and G. Faust. TFT 28, pp. 409-414 of November (1939). Abstract in QST 24, p. 39 of May (1940).

- Ignition interference suppression How it affects motor car performance.

 Wireless World (London) 46, pp.200-203 of April (1940).
- Components for radio-interference suppression devices (excluding devices for traction, marine and other special equipment). British Standard Specification No. 613 1940, revised June, 1940. Published by the British Standards Institution, Publications Department, 28 Victoria Street, London, S.W.1. Price 2 shillings net, post free 2 shillings 3 pence.
- Prevention easier than cure of radio interference. L. V. Blake. Elec. World 114, pp. 21-63 of Sept. 21 (1940). (Faulty construction of electric power lines as causes).
- How to make a mod rn interference locator. P. O'Connor. Radio Craft 12, p.418 of January (1941).
- Radio interference elimination for public utilities. (Pamphlet with advertising). Sprague Products Co., North Adams, Mass.
- Manual of interference elimination. Sprague Products Co., North Adams, Mass. Price 25 cents.
- Factors controlling man-made radioninterference. R. A. Shetzline. Bell Labs. Record, 20, 251-253 (1942).
- Pliminating electric sign radio interference. F. U. Dillon. Service, 12, 10-11 (1943).
- Dynamotor filtering. H. Goldberg. Radio News, 29, 13, (1943).
- Radio noise in small aircraft. D. K. Kinsey: Communications, 23, 34, (1943).
- Interference from power lines. J.S. Forrest. Wireless World (London), 49, 128-131, (1943).
- Aircraft radio noise filters. C.W. Fricke and S.W. Zimmerman. Communications, 23, 32, 34, (1943).
- Quiet please: W. Fernald. Radio News, 30, 1-1-42, (1943). (Suppression of electrical interference in motored vehicles. Its application in wartime and post-war problems.)
- Radio-noise filters applied to aircraft. C.W. Fricke and S.W. Zimmerman. Trans.A.I.E.E.(Elec. Engineering), 62, 590-595, (1943).
- Suppressing radio noise in the jeep. F.E. Butler. Electronics, <u>16</u>, 96-99, (1943).
- Radio bibliography-luinterference, and static. F.X. Rettenmeyer. Radio; 28, 38,40,42, (1944).

How to stop appliance static. Popular Science Monthly, 144, 188, (1944). (Vacuum cleaners, electric razors, washing machines, and neon sign interference).

Reducing machine-made interference. Wireless World (London), 50, 233, (1944).

Noise suppression on small boats. H.B. Davis. Radio News, 32, 47-49, (1944).

Radio noise-interference due to natural causes. T.W. Bennington. Wireless World (London), 50, 335-338, (1944).